Ref #	Hits	Search Query	DBs	Default Operat or	Plural s	Time Stamp
L1	616817	(stress strain load force pressure) near4 (sens\$4 detect\$4 indicat\$4 monitor\$5 measur\$5 calculat\$5 transducer gage gauge cell)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/09/15 16:51
L2	109785	((stress strain load force pressure) near4 (sens\$4 detect\$4 indicat\$4 monitor\$5 measur\$5 calculat\$5 transducer gage gauge cell)). clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/09/15 16:51
L3	25771	L1 and ((second pair two "2" double couple plurality multipl\$5 many several) near3 electrode)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/09/15 16:51
L4	262	L3 and (diamond near4 carbon)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/09/15 16:51
L5	5005	L2 and ((second pair two "2" double couple plurality multipl\$5 many several) near3 electrode)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/09/15 16:52
L6	11	L5 and (diamond near4 carbon)	US-PGPU B; USPAT; EPO; JPO	OR .	OFF	2005/09/15 16:52
L7	6465	L3 and (dielectric)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/09/15 16:52
L8	6465	L3 and (dielectric)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/09/15 16:52
L9	1089	L5 and (dielectric)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/09/15 16:52
L10	128	L7 and (diamond near4 carbon)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/09/15 16:52

L11	616817	(stress strain load force	US-PGPU	OR	OFF	2005/09/15
	010017	pressure) near4 (sens\$4 detect\$4 indicat\$4 monitor\$5 measur\$5 calculat\$5 transducer gage gauge cell)	B; USPAT; EPO; JPO	·	Orr	16:52
L12	72	L10 and (electric\$4 near2 field)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/09/15 16:52
L13	42	L12 and ((chang\$4 alternat\$4) near4 conduct\$6)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/09/15 16:52
L14	72	L10 and (electric\$4 near2 field)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/09/15 16:52
L15	2413	("DLC" near2 film) (hard near2 carbon near3 coat\$4)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/09/15 16:53
L16	237	L15 and ((second pair two "2" double couple plurality multipl\$5 many several) near3 (conductor electrode)).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/09/15· 16:53
L17	103	L16 and (dielectric)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/09/15 16:54
L18	10	L17 and ((stress strain load force pressure) near4 (sens\$4 detect\$4 indicat\$4 monitor\$5 measur\$5 calculat\$5 transducer gage gauge cell))	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/09/15 16:54
L19	3276	(silica\$4 near4 dielectric)	US-PGPU B; USPAT; EPO; JPO	OR .	OFF	2005/09/15 16:54
L20	208	L19 and ((measur\$4 sens\$4 detect\$4 calculat\$5 indicat\$5 monitor\$5) near3 resist\$5)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/09/15 16:54
L21	10	L15 near4 (shift\$4 move mov\$5 deform\$4 deflect\$4)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/09/15 16:55